

Oil Field Environmental Incident Summary

Incident: 20151205093943

Date/Time of Notice: 12/05/2015 09:39

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: OPEE 1-23H

Field Name: NORTH TIOGA

Well File #: 22182

Date Incident: 12/4/2015

Time Incident: 14:00

Facility ID Number:

County: BURKE

Twp: 160

Rng: 94

Sec: 23

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

No fluid released

Inspected:

Written Report Received: 9/23/2016

Clean Up Concluded: 12/4/2015

Risk Evaluation:

None

Areal Extent:

Burned 15 feet by 35 feet area.

Potential Environmental Impacts:

Vegetation

Action Taken or Planned:

Fire was put out.

Wastes Disposal Location: N/A

Agencies Involved: Notified NDIC on-call inspector Scott Dilhe at 9:30 AM CT 12/5/2015

Updates

Date: 12/7/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, a fire burned vegetation outside of well pad. Further followup needed to determine if report is correct stating that there was no fluid released during the incident.

Date: 12/15/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 16:15. 23 degrees F, cloudy, N wind 5-10 mph. Observed the site and took photos. It appeared that the impacts were confined to a burned CRP vegetation area east of the flare in an area approximately 50' by 20'. No petroleum impacts of the soil or vegetation were noted during the inspection. No further followup needed at this time.